INSTALLATION INSTRUCTIONS

4021 (B-PS) SIDE BAR

00-06 Suburban/Yukon XL 1/2 Ton, 02-06 Avalanche 1500 (Fits with & without cladding), 07-12 Avalanche 1500

Parts List: (1) Hardware kit including: T01 (4) 1/2" hex. head bolt QTY T07 (2) 3/8" lock washer P01 (1) Sidebar set T02 (6) M12 hex. head bolt T08 (4) Spacer washer (Driver & Passenger) T03 (10) 1/2" flat washer P02 (2) Front mounting bracket T04 (10) 1/2" lock washer P03 (2) Center mounting bracket T05 (2) 3/8" hex. head bolt P04 (2) Rear mounting bracket T06 (2) 3/8" flat washer


Tools requiered:

9/16" Socket 18mm Socket 3/4" Socket Ratchet

Instructions:

Aproximated installation time: 30 min.

- 1. Read and understand instructions completely before beginning installation.
- 2. Sidebar set consist of a driver and passenger side. Be sure to determinate the correct side before installation.
- Locate and remove the front, center and rear factory cab bolts from underside of the vehicle NOTE: for 2006 models and up, re-use the factory cab bolts to attach the brackets, for older models use the M12 bolts supplied.
- 4. Place the front, center and rear mounting brackets up to the body mount bolt locations and secure into place using M12 x 120mm hex head bolts, 1/2" flat and lock washers. Leave loose. Note: Make sure to place two spacers washers between the center mounting bracket and the steel washer of the center body mount as shown in Illustration 1.
- 5. Place the sidebar up to the front and rear mounting brackets, then secure them using 1/2" x 1 1/2" hex head bolts, flat and lock washers. Leave hardware loose. Note: For Suburban use upper slots to attach the sidebar to the mounting brackets. For Avalanche use the lower slots.
- 6. Bolt the center mounting bracket to the sidebar using 3/8 x 1" hex head bolt, flat and lock washers. Leave loose.
- 7. Make any final adjustments to the alignment of the sidebar on the vehicle and tighten the 3/8" fasteners to 30 ft/lbs., 1/2" and M12 fasteners to 65 ft./lbs. Repeat for the opposite side.
- 8. You may need to periodically re-tighten the bolts.



Revised 09/03/09

G:\Usuarios\Diseño\Instructivos PDF\37s\37079-E.Pdf

1 of 1 FODI7.003.I